



City of Tulsa Purchasing Department  
 175 E 2nd Street 15th Floor  
 Tulsa, OK 74103

IFB 24-426  
 Hydraulic Servos Overhaul or Exchange  
 for Airbus H125 Helicopter  
 Police Department  
 Bid Opening: March 28, 2024

Buyer: Darin Johnson  
[darinjohnson@cityoftulsa.org](mailto:darinjohnson@cityoftulsa.org)  
 Please contact if you have  
 any questions

**Delivery:**

If your Bid is Accepted, state the number of Days You need to deliver the Supplies and/or to begin providing Services:

You must be able to deliver the Supplies and/or Services as specified in Your Bid. Failure to do so may result in City terminating the Agreement and pursuing collection under any performance bond, as well as seeking any other damages to which it may be entitled in law or in equity.

**Pricing:**

		Helicopter Accessory Service, Inc.			Airbus Helicopters, Inc.		
Item	Description	Estimated Annual QTY	Unit Cost	Extended Cost	Estimated Annual QTY	Unit Cost	Extended Cost
1	Overhaul of Goodrich/Collins Servo Part# SC8042 - No Substitutes	2	\$14,250.00	\$28,500.00	64	\$22,533.76	\$45,067.52
2	Exchange of Goodrich/Collins Servos Part# SC8042 - No Substitutes	2	\$14,240.00	\$28,480.00	64	\$28,167.20	\$56,334.40
3	Overhaul of Goodrich/Collins Servo Part# SC5072 - No Substitutes	1	\$6,550.00	\$6,550.00	64	\$9,450.06	\$9,450.06
4	Exchange of Goodrich/Collins Servos Part# SC5072 - No Substitutes	1	\$6,550.00	\$6,550.00	64	\$11,812.57	\$11,812.57
<b>TOTAL EXTENDED COST NOT TO EXCEED:</b> (All costs must be included, or Your Bid will be disqualified)		<b>\$70,080.00</b>			<b>\$122,664.55</b>		
Delivery:		90 -120 Days			30 Days		
Annual Price Adjustment:		15%			5%		

THE CITY DOES NOT GUARANTEE ANY SPECIFIC QUANTITY OR NUMBER OF PURCHASES, IF ANY, THAT WILL BE MADE DURING THE AGREEMENT TERM.

Helicopter Accessory Service, Inc.	Airbus Helicopters, Inc.
Specify Your labor & parts warranty period: <u>Flat Rate OHC Exchange 1 Year</u>	Specify Your labor & parts warranty period: <u>Labor (N/A) embedded into Flat Rate</u>
Specify Your Overhaul & or Exchange turnaround time for the SC8042 & SC5072 Servos: <u>Estimate TAT 90 to 120 Days (If major parts not required)</u>	Specify Your Overhaul & or Exchange turnaround time for the SC8042 & SC5072 Servos: <u>Overhaul 120 Days/ Exchange is based on availability.</u>